



2.3.3 StarCom


This software is supplied with the Nova II, LaserStar, Vega and Nova with RS232 option. It allows you to measure, analyze and record power and energy from any Ophir sensor. You can log the data from each sensor simultaneously to file.



Plot of ratio of energy B/A vs. energy A



Plot of power vs. time



Histogram plot of energy distribution